

Diamond Steel CO., Inc.

971 N. George Washington Blvd. Yuba City, CA 95993 www.diamondbilt.com

> Phone: 530-674-8577 Fax: 530-674-7339

Email: sales@diamondbilt.com



DIAMOND BILT TRUCK MOUNTED EMULSION SPRAYERS

Diamond Bilt Truck Mounted Units are a great fit for the contractor with a dedicated tack service truck. These units use the truck's engine coolant to heat the tack, allowing you to heat your material while on the way to the job site. With their compact design and multiple mounting options, we have a unit that will fit any truck. Like all Diamond Bilt emulsion sprayers, these tack pots come standard with a 25' hose and a Diamond Bilt lightweight Spray Wand featuring a stay cool handle and no drip tip.

Options and customization available to make sure your unit fits all of your needs.

CALL TODAY! 530-674-8577

Diamond Steel Co, Inc. is a family owned and operated company that strives to provide well-engineered, high-quality construction equipment.

FEATURES

- Available as a Skid
- 40, 130, or 200 Gallon Tank
- Round or Cross Broken Tank for easy drainage and prevention of emulsion build-up
- Recoil Start Engine
- 4 Pass Heating Coil for even heating
- Flush/Recovery Tank for quick clean up of the pump, plumbing, hoses, and Spray Wand
- Plumbing and Spray Wand Recirculation keeps tack evenly heated and prevents emulsion from solidifying in the plumbing hose or Spray Wand
- 5' light weight Diamond Bilt Spray Wand featuring stay cool handle and no drip tip
- 25-foot Spray Wand hose
- D-Wraps for Easy Hose Storage
- Standard Color: Black

POPULAR OPTIONS

- 50-ft or 100-ft Spray Wand hose
- 115-Volt Out-of-Service Tank Heater with Thermostat
- Spring Rewind Hose Reel with Hose Guides
- · Additional Colors Available
- Call for more customizations!



Advantages of Choosing a Diamond Bilt Pave-Mate

- Quality and longevity of the units is our priority.
- Most standard parts kept in stock ready to ship.
- 1 year unlimited warranty.
- Customization and special options available.
- Knowledgeable staff to help troubleshoot any issues